

Published in Patiala Bani on 01/10/2024

TENDER NOTICE

**YADAVINDRA PUBLIC SCHOOL
PATIALA 147001**

Invites rates from contractors for renovation of Infirmary by 08 Oct 2024. Desirous parties to visit our website www.ypspatiala.in for detailed BOQ.

**BOQ FOR RENOVATION OF INFIRMARY AT
YADAVINDRA PUBLIC SCHOOL, PATIALA**

Ref : Advertisement published in the Jag Bani (Patiala Bani) on 01/10/2024

| Ser No | Nature of work | AU | Qty | Rate | Amount |
|--------|--|------|-----|------|--------|
| 1 | Dismantling of BB work built in cement mortar and removal of malba (CSR 8.39) | CuM | 4 | | |
| 2 | Dismantling of terrazo/PCC flooring and dado and removal of malba (CSR 8.40) | Sqm | 95 | | |
| 3 | Scraping of cement plaster and removing malba (CSR 8.31 (c')) | Sqm | 60 | | |
| 4 | Providing and laying anti-skid ceramic floor tiles 300 x 300x10mm (CSR 14.72) | Sqm | 28 | | |
| 5 | Providing and fixing glazed wall tiles 1' x 1'-6" (CSR 14.127) | Sqm | 120 | | |
| 6 | Providing and fixing 12mm thick prelaminated particle board in panelling (CSR 17.46(i)) | Sqm | 10 | | |
| 7 | Providing and fixing glazing 5mm thick (CSR 17.47(i)) | Sqm | 8 | | |
| 8 | Cement plaster in CM 1:6 | Sqm | 50 | | |
| 9 | Providing and laying granite 19mm thick of any colour over shelves | Sqm | 2 | | |
| 10 | Supply & fixing wooden door (Red Mirandi) and board panelled 35mm thick size 3' x 6'-9" | Nos | 4 | | |
| 11 | RCC 1: 1½ : 3 including shuttering and steel reinforcement 4" in chajja | CuM | 0.5 | | |
| 12 | Supply & fixing false ceiling over GI frame size 2'x2' with gypco tile | Sqft | 800 | | |
| 13 | PVC wall panelling of approved shade Make Décor | Sqft | 750 | | |
| 14 | Supply & fixing wooden door chowkath 3' x 7' single patam make Mirandi | Nos | 3 | | |
| 15 | Supply & fixing wooden door chowkath 3'x7' double patam make Mirandi | Nos | 1 | | |
| 16 | Supply & fixing Jali door 35mm thick size 3' x 7' make Mirandi | Nos | 1 | | |
| 17 | Providing & fixing Aluminum door shutters & window | Kg | 90 | | |
| 18 | Supply & applying 2 coats of enamel paint over one coat of primer on wooden surface | Sqm | 46 | | |
| 19 | Repair to existing wooden cabinets and 2 coats of enamel paint decorative type 10 Nos | Job | 1 | | |

| Ser No | Nature of work | AU | Qty | Rate | Amount |
|--------|---|-----|-----|------|--------|
| 20 | Supply & applying wall putty | Sqm | 100 | | |
| 21 | Making opening in terrace for sky light 2'x2' size in roof and covered with transparent acrylic sheet/polycarbonate sheet with required brickwork to make water tight with roof terrace | LS | 2 | | |
| 22 | Supply & applying 2 coats of OBD over one coat of primer | sqm | 260 | | |
| 23 | Provision & laying Brick work in CM 1:4 11.5 mm thick | sqm | 4 | | |
| 24 | Removal of sanitary fittings such as WC seats, wash basins etc(CSR 30.88) | Job | 1 | | |
| 25 | Providing and fixing in position Chinaware EWC with P or S trap of approved make with 10 ltr chinaware matching flush cistern and seat cover complete in all respect | Nos | 4 | | |
| 26 | Providing and fixing in position best Indian make white ordinary wash basin including CP-32 mm waste and one CP Brass tap/pillar cock 550 x 400mm (CSR 30.19) | Nos | 4 | | |
| 27 | Providing and fixing 32mm dia CPVC waste pipe embeded in wall upto floor level (CSR 30.19) | Nos | 4 | | |
| 28 | Providing and fixing in position best Indian make bevelled edge 5mm thick mirror mounted on walls with cromium plate studs size as peer site (CSR 30.61) | Sqm | 1.5 | | |
| 29 | Supply & fixing CP long nose bib cock 15mm | Nos | 8 | | |
| 30 | Providing and fixing CP-100mm dia grating (CSR 30.80) | Nos | 12 | | |
| 31 | Providing and fixing in position 15mm dia bib cock of best quality (CSR 30.65) | Nos | 12 | | |
| 32 | Providing and laying CPVC pipes 20mm laid in floor or mounted/embeded in walls including cost of specials (CSR 20.19) | RM | 25 | | |
| 33 | Providing and fixing CP overhead shower (round/square) with shower arm 1' (CSR 30.56) | Nos | 4 | | |
| 34 | Providing & fixing paper holder CP | Nos | 1 | | |
| 35 | Providing and fixing towel ring CP 150 - 200 mm dia (CSR 30.58 (b)) | Nos | 3 | | |
| 36 | Providing and fixing CP brass acrylic shelf size 560x130mm (CSR 30.59) | Nos | 3 | | |
| 37 | Providing and fixing in position Al/CP khunti with 3 pegs (CSR 30.63) | Nos | 4 | | |
| 38 | Supply & fixing CP soap dish | Nos | 4 | | |
| 39 | Supply & fixing 15mm CP Jet | Nos | 4 | | |

| Ser No | Nature of work | AU | Qty | Rate | Amount |
|--------|---|-----|-----|------|--------|
| 40 | Providing and fixing CP Brass extension pieces 25mm to 50mm long (CSR 30.64) | Nos | 6 | | |
| 41 | Providing and fixing Stopcock/Angle valve concealed 15mm dia (CSR 30.66) | Nos | 9 | | |
| 42 | Providing and fixing in position PVC flexible tube connection 15mm x 300 to 450mm with nuts (CSR 30.72) | Nos | 4 | | |
| 43 | Providing & fixing CP grab bar for handicaped washroom 45 cm | Nos | 1 | | |
| 44 | Supply and fixing of exhaust fan 12" dia Make Havells | Nos | 5 | | |
| 45 | Supply & fixing 4' LED lights 20w Make Havells | Nos | 6 | | |
| 46 | Supply & fixing of 2'x2' LED light 36w Make Havells | Nos | 8 | | |
| 47 | Providing and fixing electric wiring as required for lights & exhaust fan/ceiling fan | Job | 1 | | |
| 48 | Providing and fixing ceiling fan 48" Havells Breezair | Nos | 9 | | |
| 49 | Providing & fixing MCB box double door 12 way | Nos | 1 | | |

Total (incl GST)